ADC ACCESSORY DEVICE (Busbar)

Applicable MCCBs: GCB800/GCB1200

- Be sure to read the manual and warning message for safety before using products.
- This manual should be given to the person who actually uses the products and is responsible for their maintenance.

SAFETY PRECAUTION

- Before installation, wiring, operation, maintenance and inspection of the device, be sure to read the safety precautions carefully and follow the message to ensure proper operations.

-/ DANGER-


 Turn off the power before starting mounting, dismounting, wiring, maintenance or inspection. Failure to do may result in electric shocks and burns.

- CAUTION

- 1. Do not use any deformed or damaged device.
- 2. Mounting, detaching, wiring, maintaining and checking should be done by an authorized or certified person.
- It should not be used in severe environment such as high temperature, high humidity, dusty, corrosive gas, excessive vibration and impulse.
 They may result in fire or malfunction.
- 4. Use the device in a range of the rate current and pole of MCCB.
- Mounting should be done according to the instruction manual.
 Failure to mount may cause malfunction of MCCB or cause an incident which may make the operator hurt.
- 6. Please tighten the terminal screw in proper torque to prevent overheating.
- 7. Each crimp terminal or conductor pole should be connected parallel.
- When using the extended busbar, fit interphase barriers between terminals. If the breaker has no interphase barrier insulate the exposed part of the terminals or conductors with insulation sleeves tape or coating.
- Be cafeful not to be damaged by accidents during transportation or installation.
- 10. Do not modify the device unless it is permitted.
- 11. When the device become useless, it should be disposed of them as an industrial waste.

1. The Installation of the BUSBAR

- 1. Install the BUSBAR to the circuit breaker as shown in the fig. 1, 2.
- 2. Conductors should be tightened with the torque specified in the below table 1 to prevent fire accident.
- 3. Fit the barriers(sold separately) to the circuit breaker after installing the BUSBAR.
- Fit the Plate Protection(sold separately) to the circuit breaker after installing the BUSBAR. Otherwise, short circuit may accur at phase to earth






Fig.1

Tuno	Tightening torque			
Туре	Α	В		
GCB800/ GCB1200/ (NUT.HEX) (BOLT.HEX)	M10 208~477 in-lb			

Table.1 Tightening torque

Tuna	Plate protection					
Type	3P	4P				
Size(mm)	128*307	128*404				

Fig.2

 Extension BUSBAR and Plate protection kit for GCB800/GCB1200 GCBX5-FHC-N3R4-M/ GCBX5-FHC-N4X-M (sold separately)

Table.2 Plate protection

2. The Figure of installation




Fig.3 Front connection BUSBAR

* GCB800/GCB1200

Туре	A1	A2	A3	A4	B1	B2	В3	B4	B5	C1	C2	C3
Front connection	283.5	115.7			31.5	15	187	70	95	128	307	404
Front connection (GCB800/GCB1200)	283.5	115.7			31.5	15	220	70	95	128	307	

Table.3 Dimensions

Customer Center-Quick Responsive, Excellent technical support TEL_1-800-633-0405 I Home page, http://www.Automationdirect.com Specifications in this catalog are subject to change without notice due to continuous product development and improvement.