Model I G2500ST Made in Taiwan

SOLDERING TIP

PLEASE READ ALL INSTRUCTIONS AND WARNINGS BEFORE USE.

TO BEPLACE TIP

NOTE: Do not change tips while hot. Cool tip to room temperature before changing.

1. Using a screwdriver, loosen the two tip connector screws. Remove tip by sliding tip out of tip connectors.

2. Slide new tip into connectors. Using a screwdriver. firmly tighten the two tip connector screws.

3. During use, check to make sure the connector screws remain tight by occasionally retightening with screwdriver.

4. Where tip and oun connectors touch and overlap. keep the areas clean for best results.

TIN TIP BEFORE USING:

Melt solder on tip end surfaces as tip heats up but before tip reaches full heat.

A WARNING

This product, when used for soldering or similar applications. can expose you to chemicals including lead known to the State of California to cause cancer and birth defects (or other reproductive harm). For more information go to www.P65Warnings.ca.gov Note: Lead-free solder is recommended





all Lenk Corporation Kinston, N.C. 28502-3349 Fax 252-527-4189

www.wienk.com

PO Box 3349

252-527-4186

© 2021 Wall Lenk Corporation, All Rights Reserved.