Errata Sheet

This Errata Sheet contains corrections or changes made after the publication of this manual.

Product Family*:	DL05/06	**Date**:	July 10, 2013
Manual Number	D0–DCM–M		
Revision and Date	2nd Ed., September 2007		

Changes to Chapter 3. D0–DCM Setup

Page 3-9. D0–DCM Port Configuration Registers; Module Configuration Registers

In the top row of the table there is a heading named "DL05 and DL06 Option Slot". Underneath is a column named "DL05". Change that entry to "DL05 Slot 1".

(The reason for this is that the communications instructions require you to enter the slot the module occupies. In this case the DL05's only slot is slot 1.)