



PRODUCT ADVISORY

PRODUCT DISCONTINUATION ANNOUNCEMENT

Product Family:	Pneumatics	Number:	PA-PN-006
Part Numbers:	See below	Date Issued:	05/29/2026
Subject:	NITRA Actuators and Accessories Product Discontinuation	Revision:	Rev. B

Announcement

The parts listed in the following tables will be discontinued when current stock is depleted. Please refer to the table below for a **possible comparable replacement**.

The NITRA actuators and accessories listed below are being replaced with new Mindman and Metal Work brand products. Continue to monitor automationdirect.com for new NITRA replacement options as our pneumatic product line grows.

Part Numbers Affected

Discontinued NITRA Dual Guide Rod Actuators					
Discontinued NITRA Part No.	Metal Work Replacement	Replacement Type	Discontinued NITRA Part No.	Metal Work Replacement	Replacement Type
E12M010MD-M	W143012A010N	comparable	E12M050MD-M	W143012A050N	comparable
E12M020MD-M	W143012A020N	comparable	E12M075MD-M	W143012A075N	comparable
E12M025MD-M	W1430012025N	comparable	E12M100MD-M	W143012A100N	comparable
E12M030MD-M	W143012A030N	comparable	E12M125MD-M	W143012A125N	comparable
E12M040MD-M	W143012A040N	comparable	E12M150MD-M	W143012A150N	comparable

Discontinued NITRA Compact Actuators					
Discontinued NITRA Part No.	Mindman Replacement	Replacement Type	Discontinued NITRA Part No.	Mindman Replacement	Replacement Type
H12M005MD-M	MCJQ312125M	comparable	H20M030MD-M	MCJQ3122030M	comparable
H12M010MD-M	MCJQ3121210M	comparable	H20M040MD-M	MCJQ3122040M	comparable
H12M015MD-M	MCJQ3121215M	comparable	H20M050MD-M	MCJQ3122050M	comparable
H12M020MD-M	MCJQ3121220M	comparable	H20M075MD-M	MCJQ3122075M	comparable
H12M025MD-M	MCJQ3121225M	comparable	H20M100MD-M	MCJQ31220100M	comparable
H12M030MD-M	MCJQ3121230M	comparable	H25M005MD-M	MCJQ312255M	comparable
H12M040MD-M	MCJQ3121240M	comparable	H25M010MD-M	MCJQ3122510M	comparable
H12M050MD-M	MCJQ3121250M	comparable	H25M015MD-M	MCJQ3122515M	comparable
H16M005MD-M	MCJQ312165M	comparable	H25M020MD-M	MCJQ3122520M	comparable
H16M010MD-M	MCJQ3121610M	comparable	H25M025MD-M	MCJQ3122525M	comparable
H16M015MD-M	MCJQ3121615M	comparable	H25M030MD-M	MCJQ3122530M	comparable
H16M020MD-M	MCJQ3121620M	comparable	H25M040MD-M	MCJQ3122540M	comparable
H16M025MD-M	MCJQ3121625M	comparable	H25M050MD-M	MCJQ3122550M	comparable
H16M030MD-M	MCJQ3121630M	comparable	H25M075MD-M	MCJQ3122575M	comparable
H16M040MD-M	MCJQ3121640M	comparable	H25M100MD-M	MCJQ31225100M	comparable
H16M050MD-M	MCJQ3121650M	comparable	H32M005MD-M	MCJQ312325MNPT	comparable
H20M005MD-M	MCJQ312205M	comparable	H32M010MD-M	MCJQ3123210MNPT	comparable
H20M010MD-M	MCJQ3122010M	comparable	H32M015MD-M	MCJQ3123215MNPT	comparable
H20M015MD-M	MCJQ3122015M	comparable	H32M020MD-M	MCJQ3123220MNPT	comparable
H20M020MD-M	MCJQ3122020M	comparable	H32M025MD-M	MCJQ3123225MNPT	comparable
H20M025MD-M	MCJQ3122025M	comparable	H32M030MD-M	MCJQ3123230MNPT	comparable

Table continued on next page

**Part Numbers
Affected (cont'd)**

Discontinued NITRA Compact Actuators (cont'd)					
Discontinued NITRA Part No.	Mindman Replacement	Replacement Type	Discontinued NITRA Part No.	Mindman Replacement	Replacement Type
H32M040MD-M	MCJQ3123240MNPT	comparable	H63M020MD-M	MCJQ3126320MNPT	comparable
H32M050MD-M	MCJQ3123250MNPT	comparable	H63M025MD-M	MCJQ3126325MNPT	comparable
H32M075MD-M	MCJQ3123275MNPT	comparable	H63M030MD-M	MCJQ3126330MNPT	comparable
H32M100MD-M	MCJQ31232100MNPT	comparable	H63M040MD-M	MCJQ3126340MNPT	comparable
H40M005MD-M	MCJQ312405MNPT	comparable	H63M050MD-M	MCJQ3126350MNPT	comparable
H40M010MD-M	MCJQ3124010MNPT	comparable	H63M075MD-M	MCJQ3126375MNPT	comparable
H40M015MD-M	MCJQ3124015MNPT	comparable	H63M100MD-M	MCJQ31263100MNPT	comparable
H40M020MD-M	MCJQ3124020MNPT	comparable	H80M005MD-M	MCJQ312805MNPT	comparable
H40M025MD-M	MCJQ3124025MNPT	comparable	H80M010MD-M	MCJQ3128010MNPT	comparable
H40M030MD-M	MCJQ3124030MNPT	comparable	H80M015MD-M	MCJQ3128015MNPT	comparable
H40M040MD-M	MCJQ3124040MNPT	comparable	H80M020MD-M	MCJQ3128020MNPT	comparable
H40M050MD-M	MCJQ3124050MNPT	comparable	H80M025MD-M	MCJQ3128025MNPT	comparable
H40M075MD-M	MCJQ3124075MNPT	comparable	H80M030MD-M	MCJQ3128030MNPT	comparable
H40M100MD-M	MCJQ31240100MNPT	comparable	H80M040MD-M	MCJQ3128040MNPT	comparable
H50M005MD-M	MCJQ312505MNPT	comparable	H80M050MD-M	MCJQ3128050MNPT	comparable
H50M010MD-M	MCJQ3125010MNPT	comparable	H80M075MD-M	MCJQ3128075MNPT	comparable
H50M015MD-M	MCJQ3125015MNPT	comparable	H80M100MD-M	MCJQ31280100MNPT	comparable
H50M020MD-M	MCJQ3125020MNPT	comparable	H100M005MD-M	MCJQ3121005MNPT	comparable
H50M025MD-M	MCJQ3125025MNPT	comparable	H100M010MD-M	MCJQ31210010MNPT	comparable
H50M030MD-M	MCJQ3125030MNPT	comparable	H100M015MD-M	MCJQ31210015MNPT	comparable
H50M040MD-M	MCJQ3125040MNPT	comparable	H100M020MD-M	MCJQ31210020MNPT	comparable
H50M050MD-M	MCJQ3125050MNPT	comparable	H100M025MD-M	MCJQ31210025MNPT	comparable
H50M075MD-M	MCJQ3125075MNPT	comparable	H100M030MD-M	MCJQ31210030MNPT	comparable
H50M100MD-M	MCJQ31250100MNPT	comparable	H100M040MD-M	MCJQ31210040MNPT	comparable
H63M005MD-M	MCJQ312635MNPT	comparable	H100M050MD-M	MCJQ31210050MNPT	comparable
H63M010MD-M	MCJQ3126310MNPT	comparable	H100M075MD-M	MCJQ31210075MNPT	comparable
H63M015MD-M	MCJQ3126315MNPT	comparable	H100M100MD-M	MCJQ312100100MNPT	comparable

Discontinued NITRA Compact Actuator Accessories					
Discontinued NITRA Part No.	Mindman Replacement	Replacement Type	Discontinued NITRA Part No.	Mindman Replacement	Replacement Type
HRC-12M		No	HFC-12M	CBJ112	comparable
HRC-16M		No	HFC-16M	CBJ116	comparable
HRC-20M		No	HFC-20M	CBJ120	comparable
HRC-25M		No	HFC-25M	CBJ125	comparable
HRC-32M		No	HFC-32M	CBJ132	comparable
HRC-40M		No	HFC-40M	CBJ140	comparable
HRC-50M		No	HFC-50M	CBJ150	comparable
HRC-63M		No	HFC-63M	CBJ163	comparable
HRC-80M		No	HFC-80M	CBJ180	comparable
HRC-100M		No	HFC-100M	CBJ1100	comparable

**Part Numbers
Affected (cont'd)**

Discontinued NITRA Rotary Actuators					
Discontinued NITRA Part No.	Mindman Replacement	Replacement Type	Discontinued NITRA Part No.	Mindman Replacement	Replacement Type
J10MD-M	MCRQ16A	comparable	J50MD-M	MCRQ25ANPT	comparable
J10MD-MA	MCRQ16R	comparable	J50MD-MA	MCRQ25RNPT	comparable
J20MD-M	MCRQ20ANPT	comparable	J10M-SA		No
J20MD-MA	MCRQ20RNPT	comparable	J2030M-SA		No
J30MD-M	MCRQ20ANPT	comparable	J50M-SA		No
J30MD-MA	MCRQ20RNPT	comparable			

Discontinued NITRA Parallel Grippers					
Discontinued NITRA Part No.	Mindman Replacement	Replacement Type	Discontinued NITRA Part No.	Mindman Replacement	Replacement Type
KP06MD-M	MCHC6	comparable	KP06MD-MB		No
KP10MD-M	MCHC10	comparable	KP10MD-MB	MCHC103	comparable
KP16MD-M	MCHC16	comparable	KP16MD-MB	MCHC163	comparable
KP20MD-M	MCHC20	comparable	KP20MD-MB	MCHC203	comparable
KP25MD-M	MCHC25	comparable	KP25MD-MB	MCHC253	comparable
KP32MD-M	MCHC32	comparable	KP32MD-MB	MCHC323	comparable
KP40MD-M	MCHC40	comparable	KP40MD-MB	MCHC403	comparable
KP06MSC-M		No	KP06MSC-MB		No
KP10MSC-M		No	KP10MSC-MB		No
KP16MSC-M		No	KP16MSC-MB		No
KP20MSC-M		No	KP20MSC-MB		No
KP25MSC-M		No	KP25MSC-MB		No
KP32MSC-M		No	KP32MSC-MB		No
KP40MSC-M		No	KP40MSC-MB		No
KP06MSA-M		No	KP06MSA-MB		No
KP10MSA-M		No	KP10MSA-MB		No
KP16MSA-M	MCHC16S	comparable	KP16MSA-MB		No
KP20MSA-M		No	KP20MSA-MB		No
KP25MSA-M		No	KP25MSA-MB		No
KP32MSA-M		No	KP32MSA-MB		No
KP40MSA-M		No	KP40MSA-MB		No

Discontinued NITRA Angular Grippers					
Discontinued NITRA Part No.	Mindman Replacement	Replacement Type	Discontinued NITRA Part No.	Mindman Replacement	Replacement Type
KA06MD-M		No	KA06MSA-M		No
KA10MD-M	MCHA12	comparable	KA10MSA-M		No
KA16MD-M	MCHA16	comparable	KA16MSA-M		No
KA20MD-M	MCHA20	comparable	KA20MSA-M		No
KA25MD-M	MCHA25	comparable	KA25MSA-M		No
KA32MD-M	MCHA32	comparable	KA32MSA-M		No

**Technical
Assistance**

If you have any questions regarding this Product Advisory, please contact Technical Support at 770-844-4200 or 800-633-0405 for further assistance.