


M12A INPUT	POWER	MASTER POWER - STROBE
PIN-1 (BROWN)	+24 VDC	+24 VDC
PIN-2 (WHITE)	NOT CONNECTED	TRIGGER NPN
PIN-3 (BLUE)	0 VDC	0 VDC
PIN-4 (BLACK)	NOT CONNECTED	TRIGGER PNP



LUMHER BD MACHINE VISION LIGHTING

BD1PD5CY

AutomationDirect.com  
1-800-633-0405