


M12A INPUT POWER MASTER POWER - STROBE

PIN-1 (BROWN)	+24 VDC	+24 VDC
PIN-2 (WHITE)	NOT CONNECTED	TRIGGER NPN
PIN-3 (BLUE)	0 VDC	0 VDC
PIN-4 (BLACK)	NOT CONNECTED	TRIGGER PNP



LUHMER BD MACHINE VISION LIGHTING

BD2PD5CY

AutomationDirect.com
1-800-633-0405