



Errata Sheet

This Errata Sheet contains corrections or changes made after the publication of this manual.

Product Family: Terminator I/O Profibus DP Base Controller Manual
Manual Number T1H-PBC-M
Revision and Date 1st Ed., Rev. A; April 2004


Date: March 20, 2013

Changes to CHAPTER 1: Introduction

Pages 1-7. Introduction; T1H–Profibus Base Controller:

The T1H-PBC module faceplate changed. The status indicator named “HOLDING TOKEN” was changed to “LINK GOOD”. The status indicator function did not change.

For example, replace the drawing on page 1-7 with this one:



Pages 1-6, 2-3, 2-4, and 2-5 all have drawings showing the old faceplate. “HOLDING TOKEN” is also referred to on pages 2-10 and A-2. Change all references to “HOLDING TOKEN” to “LINK GOOD”.