



WL **Lenk** **Soldering Tip**

TO REPLACE TIP

Unscrew old tip and screw new tip securely.

TIN TIP BEFORE USING

Melt solder on tip end surfaces as tip heats up but before tip reaches full heat.

AFTER USE

To prevent tip from "freezing" in iron, apply graphite to threads on tip and loosen tip after each use. Tighten tip before using again.



⚠ WARNING

This product when used for soldering or similar applications, can expose you to chemicals including lead known to the State of California to cause cancer and birth defects (or other reproductive harm). For more information go to www.P65Warnings.ca.gov

NOTE: Lead free solder is recommended.



Wall Lenk Corporation

PO Box 3349
252-527-4186

Kinston, N.C. 28502-3349
Fax 252-527-4189

© 1999 Wall Lenk Corporation. All Rights Reserved.