



# **WL** **Lenk** **Soldering Tip**

## **TO REPLACE TIP**

Unscrew old tip and screw new tip securely.

## **TIN TIP BEFORE USING**

Melt solder on tip end surfaces as tip heats up but before tip reaches full heat.

## **AFTER USE**

To prevent tip from "freezing" in iron, apply graphite to threads on tip and loosen tip after each use. Tighten tip before using again.



## **⚠ WARNING**

This product when used for soldering or similar applications, can expose you to chemicals including lead known to the State of California to cause cancer and birth defects (or other reproductive harm). For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov)

NOTE: Lead free solder is recommended.



# **Wall Lenk Corporation**

PO Box 3349  
252-527-4186

Kinston, N.C. 28502-3349  
Fax 252-527-4189