

Product Advisory

Product Family: DirectLOGIC DL205 Series

Part Numbers: H2-CTRIO2

Subject: Hardware Issue Revision: Original

Purpose

All H2-CTRIO2 modules with 5Ax Hardware revision have a manufacturing defect.

Affected Products

Part Number Affected Versions

H2-CTRIO2 HW Rev 5Ax

Summary

All H2-CTRIO2 modules with 5A hardware revision have a manufacturing defect. If wired in a certain configuration the module will not function properly.

Solution

All H2-CTRIO2 modules with 5Ax Hardware rev should be returned for replacement. See images for HW Rev identification.





Product Description

The DirectLOGIC product line is the original PLC family provided by AutomationDirect. This product was started in the 1980's.

Technical Assistance If you have any questions regarding this Product Advisory, please contact Technical Support at 770-844-4200 or 800-633-0405 for further assistance.

PA-DL-008

07/24/2024

Number:

Date Issued: