



Product Advisory

Product Family:	GS30 VFDs	Number:	PA-GS-023
Part Numbers:	See below	Date Issued:	01/28/2026
Subject:	Incorrect wiring label	Revision:	Original

Purpose Certain GS33 models have an incorrect label above the input power connections.

Part Numbers Affected GS33-2030, GS33-4040

Summary GS33-2030 with serial numbers GS332030+K25050001 through GS332030+K25050065. These units have a sticker above the R/L1, S/L2, T/L3 and U/T1, V/T2, W/T3 terminals indicating incorrect Power voltage of 460 VAC instead of correct voltage of 230 VAC.

GS33-4040 with serial numbers GS334040+K25050001 through GS334040+K25050010. These units have a sticker above the R/L1, S/L2, T/L3 and U/T1, V/T2, W/T3 terminals indicating incorrect Power voltage of 230 VAC instead of correct voltage of 460 VAC.

Solution Contact AutomationDirect.com technical support for corrected replacement labels.

Technical Assistance If you have any questions regarding this Product Advisory, please contact Technical Support at 770-844-4200 or 800-633-0405 for further assistance.