


**M12A INPUT      POWER      MASTER POWER - STROBE**

PIN-1 (BROWN)	+24 VDC	+24 VDC
PIN-2 (WHITE)	NOT CONNECTED	TRIGGER NPN
PIN-3 (BLUE)	0 VDC	0 VDC
PIN-4 (BLACK)	NOT CONNECTED	TRIGGER PNP



**LUHMER BD MACHINE VISION LIGHTING**

**BD2ZD5CY**

AutomationDirect.com  
1-800-633-0405