




- 1 = OUTPUT INDICATOR (DC OK, GREEN)  
 2 = OUTPUT LOW VOLTAGE INDICATOR (DC LOW, RED)  
 3 = OUTPUT VOLTAGE ADJUSTER (V.ADJUST)



ISOMETRIC VIEW

RHINO POWER SUPPLIES

PSRS-12-15

AutomationDirect.com  
 1-800-633-0405