







DETAIL A
SCALE 2 : 3



DETAIL B
SCALE 2 : 3



DETAIL C
SCALE 2 : 3

M12A INPUT	POWER	MASTER POWER - STROBE
PIN-1 (BROWN)	+24 VDC	+24 VDC
PIN-2 (WHITE)	NOT CONNECTED	TRIGGER NPN
PIN-3 (BLUE)	0 VDC	0 VDC
PIN-4 (BLACK)	NOT CONNECTED	TRIGGER PNP

LUMHER RD MACHINE VISION LIGHTING

RD2PD5CY

AutomationDirect.com
1-800-633-0405