



BK = BLACK

BN = BROWN

BU = BLUE








DETAIL A
SCALE 2 : 1.5



DETAIL B
SCALE 2 : 1.5

ISOMETRIC VIEW



di-soric SENSOR SIGNAL CONVERTERS

TKHM-Z_TSM-Z_UN

AutomationDirect.com
1-800-633-0405



3rd
ANGLE

NOT TO
SCALE

PART DIMENSIONS MAY DIFFER SLIGHTLY
DUE TO MANUFACTURER'S VARIANCES

METRIC UNITS USED
FOR PART DESIGN

UNLESS OTHERWISE
SPECIFIED UNITS ARE: **mm**
[inch]

MODEL
REV. --

DRAWING DATE
9/12/2025

SHEET 1 OF 1