


5-POLE MALE M12  
QUICK DISCONNECT





SENSOR MAIN



CONTROLLER

5-POLE FEMALE M12  
QUICK DISCONNECT



SECONDARY SENSOR

5-POLE FEMALE M12  
QUICK DISCONNECT



WENGLOR LASER MEASUREMENT SENSORS

ZC4G004

AutomationDirect.com  
1-800-633-0405

3rd ANGLE	NOT TO SCALE	PART DIMENSIONS MAY DIFFER SLIGHTLY DUE TO MANUFACTURER'S VARIANCES	METRIC UNITS USED FOR PART DESIGN	UNLESS OTHERWISE SPECIFIED UNITS ARE: <b>mm</b> [inch]	MODEL REV. --	DRAWING DATE 3/25/2025	SHEET 1 OF 1
--------------	-----------------	--	--------------------------------------	--	------------------	---------------------------	--------------