


bimed BRM Cable Plate Assembly Instructions

Views



Instructions

1a




1b



Step 1.a. Attach the cable plate to the enclosure via snap-fit.

Step 1.b. Attach the cable plate to the enclosure via 4 screws.

3



Step 3.1. Choose the optimized cable according to seals clamping ranges and prepare cable for installation.

Step 3.2. Insert the cable through the seal.