



Errata Sheet

This Errata Sheet contains corrections or changes made after the publication of this manual.

Product Family: DL305
Manual Number D3-ANLG-M
Revision and Date 3rd Edition, February 2003

Date: July 25, 2024

July 25, 2024

Changes to Chapter 5. F3-16AD-1 16-Channel Analog Input

This module is no longer available. Please consider the BRIX or CLICK systems as a replacement

June 28, 2024

Changes to Chapter 4. F3-08AD-1 8-Channel Analog Input

This module is no longer available. Please consider the F3-04ADS as a replacement

September 2018

Changes to Chapter 2. D3-04AD 4-Channel Analog Input

This module is no longer available. Please consider the F3-08AD-1 or F3-04ADS as a replacement


Changes to Chapter 3. F3-04ADS 4-Channel Isolated Analog Input

Page 3-3. Setting the Module Jumpers; Jumper Locations

The PC board was redesigned and the locations of jumpers J10, J11, J12, and J13 changed. The jumpers were rotated 90 degrees and are closer to the back of the module than the original layout. The functionality of the jumpers did not change. The orientation of the 5 pairs of pins for each channel is the same.

The photo on the right shows the new design, while the one on the left shows the original PC board. The photo on the left matches the drawing shown on page 3-3. The redesigned PC boards are in modules manufactured starting in mid-2012.

**Original PC Board Layout
(Manufactured prior to mid-2012)**



**Redesigned PC Board Layout
(Manufactured after mid-2012)**

