



Errata Sheet

This Errata Sheet contains corrections or changes made after the publication of this manual.

Product Family:	DL405	Date:	June 1, 2020
Manual Number	D4-HSC-M		
Revision and Date	Revision A, June 2020		

Changes to Chapter 7. Program Applications

Page 7-2. A Quick Checkout of the Module; Wiring Diagram for Example

The wiring diagram shows +24 VDC going to terminal INA-. This is incorrect; it should be -24 VDC.

Changes to Chapter 1, Getting Started; Chapter 2, Installation and Wiring

Added Note: D4-454 CPU will only support D4-HSC module firmware v2.3