


172541

Check list



X1



X1



X1



X1




X4



X1

Note:

Please refer to below illustration about the ideal mounting position and movable range.




360°

Please don't have this pencil tray mounted out of the edge of desk.


Step 1

Fasten the axis under the solid desk with the screws.




Step 2


Insert the small axis into the adhesive tape and insert them into the groove then.



The max. diameter of adhesive tape is 1".




The assembly is completed when you hear a click.




Step 3

Insert the tape cutting blade in the tray. (as figure show as below)



Caution: Be aware that the tape cutting blade is sharp; careless use may result in injury.



Step 4

Fasten another axis with the one mounted under the desk with one screw to fasten the pencil tray between.

