




# SHIELDED FIELD WIREABLE CONNECTOR ASSEMBLY INSTRUCTIONS

Use the illustrations below to properly assemble these connectors.



Strip wires and cut to the lengths shown to ensure a good fit when the connector is assembled.



1-800-633-0405

www.automationdirect.com