



# Errata Sheet

This Errata Sheet contains corrections or changes made after the publication of this manual.

---

<b>Product Family:</b>	DirectLOGIC PLCs	<b>Date:</b>	June 14, 2012
<b>Manual Number</b>	HX-ECOM-M		
<b>Revision and Date</b>	3rd Ed., Rev.C, June 2011		

---

## **Changes to Chapter 2. Setup and Installation**

Page 2-8. Inserting the ECOM Module in the PLC Base; DL205 Slot Choices

*Add the following note just below the table at the top of the page:*

"Note: Also compatible with obsolete bases D2-0xB, D2-0xBDC-1 and D2-0xBDC-2."