



# Errata Sheet

This Errata Sheet contains corrections or changes made after the publication of this manual.

---

<b>Product Family:</b>	OptiMate	<b>Date:</b>	May 29, 2012
<b>Manual Number</b>	OP-1212-M		
<b>Revision and Date</b>	Rev B., May 2010		

---

## Changes to “Installing the Panel”

Pages 10, 11, 12 and 13. PLC to Panel Cable and Choosing the Proper Connecting Cables

*Cable OP-4CBL-2 is no longer available. Consider using AutomationDirect cable EA-4CBL-2 for a comparable replacement.*