## **SHIMPO** Handheld Tachometers

## PT-110 Non-Contact Laser Tachometer

The Shimpo Model PT-110 Non-Contact Laser Tachometer is a simple-to-use, ergonomic, rugged test instrument that operates with optical laser technology. This velocity analyzing and measuring device is ideal for rotational machine inspection and process speed analysis. The PT-110 features a large backlit LCD screen that provides clear viewing in any environment. Users can obtain results in either Hertz or RPM, as well as Total counts with the simple selection switch. During testing, the unit automatically saves maximum, minimum, last recorded values and up to 96 logged data readings. The compact, lightweight PT-110 Tachometer comes standard with reflective tape, 3 AAA batteries and protective carrying case.

## **Features**

- Measures RPM, Hz or Total by simple adjusting selector switch
- Lightweight, ergonomic design allows comfortable long term usage
- Large, backlit LCD for easy viewing in both bright and dim environments
- Automatically records Maximum, Minimum, Last Value as well as up to 96 data points during testing. Quickly review after testing by pushing the MEM button.
- Laser operation shows point of measurement for easy aiming on equipment



PT-110

PT-110 Specifications				
Display Range	2.5 - 99,999 RPM; 0.05 - 1666 Hz; 1 - 99999 Count			
Resolution	0.1 RPM (2.5 - 999.9 RPM) 1 RPM (above 1000 RPM) 0.01 Hz (0.05 - 99.99 Hz) 0.1 Hz (above 100 Hz)			
Display	5 digit, 0.7 in. (18 mm) LCD			
Accuracy	± 0.05% + 1 digit			
Sampling Time	0.8 second (over 60 RPM)			
Detection	Laser			
Measuring Distance	2 - 20 in. (50 - 500 mm)			
Memory	Automatically stores Maximum (UP), Minimum (DN), last value (LA) and up to 96 readings for review. Maximum speed for reading storage is every 0.8 seconds.			
Dimensions	6.1 in. L x 2.8 in. W x 1.4 in. H (155 mm x 70 mm x 35 mm)			
Power	(3) AAA 1.5V batteries			
Enclosure	ABS plastic housing			
Operating Temperature	32 - 104 °F (0 - 40 °C)			
Weight	0.4 lb (181 g)			
Agency Approvals	N/A			
Included Accessories	(3) AAA alkaline batteries, protective carrying case, reflective tape.			

PT-110 Accessories		
Part Number	Description	Price Each
DT-TAB	Reflective tabs, sheet of (35) 1/2-inch squares, for use with Shimpo DT-205LR, DT-207LR and PT-110 handheld tachometers	
DT-TAPE	Replacement reflective tape strip, 1 x 7-3/4 inch, for use with Shimpo DT-205LR, DT-207LR and PT-110 handheld tachometers	

PT-110 Handheld Tachometer		
Part Number	Description	Price
PT-110	Handheld tachometer, non-contact, 5-digit LCD display	

